Inch By Inch Inspections Home Inspection Report





1681 Medallion Court, Mississauga, Ontario

Inspection prepared for: Jeff Johnston Real Estate Agent: Jeff Johnston - Remax

Date of Inspection: 5/11/2023 Time: 2:00pm

Inspector: Tony Muscat 6150 Hwy 7, Vaughan, Ontario L4H0R6 Phone: 416-826-7172 Email: inchbyinch2006@gmail.com

Table Of Contents

General Information	2
Exterior	3-11
Roof	12-13
Garage	14-16
Chimney	17
Basement	18-21
Fireplace	22
Plumbing	23-24
Electrical	25-28
Heating	29-31
Air Conditioning	32
Water Heater	33
Other Interior Areas	34-39
Attic	40-41
Additional Comments	42-45
Insurance Information	46
Glossary	47

Inch E	3v I	nch	Inst	oecti	ons
	- ,		vr		0.10

General Information

1. Inspector

Tony Muscat, CMI Inch by Inch Inspections Inc. 1-888-445-0737 416-826-7172

www.inchbyinchinspections.com www.commericalinspectionstoronto.com

info@inchbyinchinspections.com

Legend for Info: Serv is Serviceable Ni is Not Inspected Np is Not Present Rev is Review

2. Persons in Attendance

Listing Agent

3. Occupancy

The Property is occupied

4. Property Information

This is a single family home

5. Levels

2 Storey

6. Approx size of home

Materials: Approx 2400

7. Estimated Age


Approx 50

8. Weather conditions

Clear • Cloudy

9. Temperature

_	Serv	NP	NI	Rev	None	Observations:
	Х					• 20C



Page 3 of 47

()Good at time of inspection in visible areas only. ()Good at time of inspection in visible areas only.

4. Trim Conditions

Х

Rev	None	Materials: Vinyl and Metal
		Observations:

• ()Suggest preventative maintenance(check) on a yearly basis

• ()Suggest sealing/caulking as part of routine maintenance to prevent further deterioration.

()Suggest sealing/caulking as part of routine maintenance to prevent further deterioration.

⁽⁾Suggest sealing/caulking as part of routine maintenance to prevent further deterioration.





1681 Medallion Court, Mississauga, Ontario



()Suggest sealing/caulking as part of routine maintenance to prevent further deterioration.

5. Window/Frame Conditions

	X	NP	NI	Rev	None	 Materials: Vinyl Frame Observations: ()Windows are vinyl and seem in good working order of time of inspection. Several random windows were checked and are in good operating order. Suggest yearly lubrication to maintain gear of window. Caulking and maintaining the windows on a semi annual basis is recommended due to possible water intrusion in the home if chalking is not in good order that can result in window damage or interior damage. ()Recommend all window well or wells to have a plastic cover(window well cover) and or a safety grate. Semi annual maintenance is needed to assure window wells are free of weeds and grading is below the window.
--	---	----	----	-----	------	--

1681 Medallion Court, Mississauga, Ontario



()Windows are vinyl and seem in good working order of time of inspection.

Several random windows were checked and are in good operating order.

Suggest yearly lubrication to maintain gear of window.

Caulking and maintaining the windows on a semi annual basis is recommended due to possible water intrusion in the home if chalking is not in good order that can result in window damage or interior damage.



()Windows are vinyl and seem in good working order of time of inspection.

Several random windows were checked and are in good operating order.

Suggest yearly lubrication to maintain gear of window.


Caulking and maintaining the windows on a semi annual basis is recommended due to possible water intrusion in the home if chalking is not in good order that can result in window damage or interior damage.



()Recommend all window well or wells to have a plastic cover(window well cover) and or a safety grate. Semi annual maintenance is needed to assure window wells are free of weeds and grading is below the window.

Materials: Metal Clad

6. Exterior Door Conditions




Observations: • ()All doors or door need yearly maintenance to prolong the life of the door and the functionality.

7. Gutter Condition
Serv NP NI Rev None X Image: None Materials: Galvanized Observations: • ()All gutters need yearly check and caulking. Monitor and address as needed. • ()It is recommended to provide downspout extension 4 to 6 feet away from the home for proper water drainage.
()It is recommended to provide downspout extension 4 to 6 feet away from the home for proper water drainage.
8. FenceCondition
X Materials: Chain Link • Metal Observations: • Aged
leaning
9. Electric Meter Condition
X Location: Left Side Observations: • ()Digital meter 200amp service from city 240 volt 1 phase, 3 phase. Top of unit rusted.
Page 7 of 47




()Digital meter 200amp service from city 240 volt 1 phase, 3 phase. Top of unit rusted.



13. Door Bell Condition
Serv NP NI Rev None Location: Front
X Observations: • ()Door bell is in good working order at time of inspection
14. Lot Grade and Drainage Conditions
 Serv NP NI Rev None Closervations: ()Adding dirt backfill (stone)to any low lying areas located around the foundation is recommended to ensure proper drainage away from the foundation at all times. Monitor on a yearly basis. ()Regrading where needed is recommended to assure all water drains away from the homes foundation at all times. It is recommended to monitor grading to help prevent water entry into the home.
15. Foundation Conditions
Serv NP NI Rev None X Image: Server in the s
16. Retaining Wall Conditions
Serv NP NI Rev None X
17. Patio Conditions
X None X Image: None Observations: • ()The patio condition is in good condition at time of inspection unless noted. Continue maintenance on the patio and monitor for sloping. • ()Continue maintenance as needed to prolong the life of the patio Image: None • ()Continue maintenance as needed to prolong the life of the patio Image: None Image: None • ()Continue maintenance as needed to prolong the life of the patio Image: None Image: None Image: None Image: None • ()Continue maintenance as needed to prolong the life of the patio Image: None <
()Continue maintenance as needed to prolong the life of the patio
18. Deck Condition

Serv	NP	NI	Rev	None
				Х





rear

Roof

1. Methods Used to Inspect Roof

How Inspected: ()Ground level view. • ()Camera viewed. If the roof is too high, is too steep, or wet, or is composed of materials which can be damaged if walked upon, the roof is not mounted. Therefore, client is advised that this is a limited review and a licensed roofer should be contacted for more detail prior to purchase.

2. Roof Condition

Serv	NP	NI	Rev	None	Materials: Asphalt Composition Shingles
XI					Observations:
7.					• ()Shingles are in good condition in visible areas only at time of inspection
					()Shingles are in good conduction in visible areas only at time of inspection

unless noted. Continue a yearly checkup and regular maintenance to prolong the life of the roof.




()Shingles are in good condition in visible areas only at time of inspection unless noted. Continue a yearly checkup and regular maintenance to prolong the life of the roof.

3. Roof Flashing Condition
Serv NP NI Rev None X Image: None Materials: Galvanized Observations: Observations: • ()Typical maintenance necessary, on an annual or semi-annual basis. This generally consists of resealing gaps at through-the-roof projections and at the parapet walls as necessary.
4. Skylight Condition
Serv NP NI Rev None
5. Roof Surface Conditions
Serv NP NI Rev None X Image: Server of the s



()Good at time of inspection only in visible areas only.




6. Roof Comments

Serv	NP	NI	Rev	None
Х				

Observations: ()Roof shingles are in good condition at time of inspection in visible areas only.

1681 Medallion Court, Mississauga, Ontario

Garage
1. GarageType
Type: Attached
2. Garage Roof Condition
X Materials: Asphalt Composition Shingles
3. Garage Exterior Conditions
X NP NI Rev None X Observations: • ()Good at time of inspection.
4. Gutter/ Downspout Conditions
X NP NI Rev None Observations: • ()Same as house
5. Garage Floor Condition
Serv NP NI Rev None X A A A A A Y A B B A A B Y B
6. Garage Door Condition
X NP NI Rev None Observations: • ()Good at time of inspection in visible areas only.
7. Garage Door Hardware Condition
X Observations: • ()The hardware for the door is in good condition at time of inspection unless noted.
8. Garage Door Opener Condition
Serv NP NI Rev None X Image: Serve in the serve
9. Garage Window Conditions
Serv NP NI Rev None X I I I
10. Exterior Door Condition
X NP NI Rev None Observations: • ()Door is in good condition at time of inspection.
11. Fire Door Conditions
Serv NP NI Rev None
Page 14 of 47





()Dry at the time of the inspection in visible areas only.



Staining noted. Dry at time of inspection.

1681 Medallion Court, Mississauga, Ontario

15. Garage Electrical Condition

Serv NP NI Rev None

16. Garage Comments Serv NP NI Rev None

Serv	NP	NI	Rev
Х			

Observations:

• ()Grease all moving components of the garage door to prolong the life of the door.

• ()It is recommended never to store combustible items in the the garage such as propane tanks gasoline and any flammable liquid.

17. Step-Stairs

Serv	NP	NI	Rev	None
				Х

Inch B	Inch	Inspections
		inspections

Chimney

Type: Brick chimney

2. Chimney Condition Serv NP NI Rev None Observations: ()Chimney is in good condition in visible areas only at time of inspection Х unless noted. Continue yearly checkup to maintain life of chimney. 3. Flue Condition NP NI Serv Rev None Materials: Undetermined Х Observations: • ()Unable to determine condition or presence of liner due to accessibility. 4. Flashing Conditions Serv NP NI Rev None Materials: Galvanized Х Observations: ()Typical maintenance is needed and on an annual or semi-annual basis. This generally consists of resealing gaps at through-the-roof projections and at the parapet walls as necessary. 5. Spark Arrester/Raincap Condition NI Rev None Serv Rain Cap Present Observations: Х ()Rain cap present. 6. Chimney Comments NP Serv NI Rev None Observations: ()Limited review, chimney was viewed from the ground only. Our chimney Х review is limited to visible accessible components only. If further review is desired, we suggest review by a qualified professional prior to close. (A)Refer to WETT certified ()Limited review, chimney was viewed from the ground only. Our chimney review is limited to visible accessible components only. If further review is desired, we suggest review by a qualified professional prior to close.

Inch By Inch Inspections 1681 Medallion Court, Mississauga, Ontario **Basement** 1. Basement Access Basement stairway. 2. Foundation Comments Serv NP NI Rev None Type: Unfinished • Finished Basement Observations: Х • ()Finished basement: finished areas in basement were observed. Access to the original basement walls, floors, and ceilings was not available due to the additional construction that is present such as framed out walls, covered ceilings, and added floor coverings. As these areas are not visible or accessible to the inspector they are limited from this inspection. • ()Inaccessible areas behind walls, ceilling and floor coverings are not within the scope of this report. ()Limited view due to storage of personal property. 3. Basement Stairs Condition Serv NP NI Rev None Observations: ()Good at time of inspection in visible areas only. Х Х ()loose ()loose 4. Basement Floor Condition Serv None Materials: Carpet • Concrete Observations: Х • ()Dry at time of inspection in visible areas only. • ()Minor cracking to tiled floor can occur at anytime by someone dropping something or placing something heavy on floor. It is considered a minor cosmetic issue and not within the scope of this inspection as it focuses on basic structure and major systems only unless otherwise noted • ()Storage blocking in basement at time of inspection. 5. Basement Walls Condition Serv Rev None Materials: Concrete • Drywall • Finished basement. Observations: Х ()Dry at time of inspection unless noted.

1681 Medallion Court, Mississauga, Ontario

<image/>
()Dry at time of inspection unless noted. ()Dry at time of inspection unless noted.
6. Basement Ceilings Condition
Serv NP NI Rev None Materials: Drop Tile • Wood
X Observations: • ()Dry at the time of the inspection in visible areas only unless noted.
7. Exterior Doors Condition
Serv NP NI Rev None
8. Joist Condition
Serv NP NI Rev None Materials: Finished basement unable to determine.
X Observations: • ()Finished basement unable to determine.
9. Beams Condition
Serv NP NI Rev None Materials: Metal • Finished basement.
X Observations:
• ()Finished basement unable to determine.
10. Support Post Comments
Serv NP NI Rev None Materials: Metal • Finished basement.
X Observations: • ()Finished basement unable to determine.
U U
11. Subfloor Condition Serv NP NI Rev None
12. Window Condition
Serv NP NI Rev None Style: Vinyl Frame
X Observations: • ()Suggest caulking around doors and windows as necessary.
13. Electrical Conditions
X • ()Electrical is in good condition in visible areas at time of inspection unless
noted.consult a qualified electrician as needed

Page 19 of 47

14. Visible Plumbing Condition

Serv	NP	INI	Rev	None	. N.
					ייו
V					C

Materials: Copper in visible areas only. • ABS where visible. Observations:

• ()Visible plumbing is working at time of inspection unless noted in visible areas only.

• ()Basement floor drain. It is recommended never to cover the floor drain for safety and emergency purposes.



()Basement floor drain. It is recommended never to cover the floor drain for safety and emergency purposes.


15. Insulation Condition

Materials: Unable to determine due to finished basement.

Х		Х	O
			• (

Observations: • ()Unable to determine due to finished basement.

Missing



Missing

Missing

Missing vapour barrier
16. Distribution/Ducts
X Ducts/Registers Observations: • ()Ducts are in good shape in visible areas only at time of inspection were visible at time of inspection unless noted.
17. Basement Comments
Serv NP NI Rev None X Image: Serve and the s
18. Cold Cellar
Serv NP NI Rev None

Fireplace

1. Fireplace Location

Location: The fireplace is located in the Family Room.

2. Fireplace Style

Style: Masonry

3. Fireplace Comments

_	Serv	NP	NI	Rev	None	
ſ	Х					• (

Observations:
()WETT,A wood- burning fireplace or wood stove is noted in this home.
Please be advised that this item may only be lawfully inspected by a WETT certified contractor and then, only after a thorough cleaning. It is strongly suggested that this fireplace and chimney be cleaned and inspected before close or use. Consult a qualified contractor for current standards.




()WETT,A wood- burning fireplace or wood stove is noted in this home. Please be advised that this item may only be lawfully inspected by a WETT certified contractor and then, only after a thorough cleaning. It is strongly suggested that this fireplace and chimney be cleaned and inspected before close or use. Consult a qualified contractor for current standards.

1681 Medallion Court, Mississauga, Ontario

Plumbing
1. Main Shutoff Location Sev NP Ne I I Materials: Copper where visible Observations: I Basement Area
Basement Area
 2. Supply Line Condition Serv NP NI Rev None X A Base None X Base None Materials: Copper, where visible Observations: Supply line is in good condition at time of inspection, in visible ares only unless noted.
3. Waste Line Conditions
X NP NI Rev None X Observations: • ()Waste lines are in good condition at time of inspection in visible areas only.
4. Waste Line Condition
Serv NP NI Rev None X Attrials: ABS, where visible. Observations: • ()Good condition at time of inspection at visible areas only unless noted. • ()It is recommended to inspect all main drains - weeping tiles if possible with a camera system to assure free flow of water .Consult a qualified contractor. It is recommended to install a back flow preventer in the home drainage system.
5. Venting Conditions
Serv NP NI Rev None X Image: Serve transmission of the serve


6. Plumbing Comments
X Comments: • ()All tested plumbing components tested good at time of inspection unless otherwise noted. Monitoring for aging and maintenance is needed on a
ongoing basis. • ()It is recommended to install a back flow preventer on all main sewage lines to help prevent sewage backup. Consult a licenced plumber. • ()It is recommended to never block floor drains at all times in case of an plumbing emergency.
• ()Monitoring plumbing system periodic is recommended and as they age.



Panel

()Verifying if the panel is labled correctly is recommended.

200 amp



()Double tapping observed. Double tapping (i.e. 2 wires on a single pole breaker) can add to the load of the affected circuit causing a possible overload and tripping breakers, or result in loose connections and overheating of the breaker or connections. Ideally, doubled-up circuits should be independently fused or breaker. Consult a licenced electrician.

1681 Medallion Court, Mississauga, Ontario




Rust noted in panel.



Rust noted in panel.



()Verifying if the panel is labled correctly is recommended.







Observations: • ()Verifying if the panel is labled correctly is recommended.



()Verifying if the panel is labled correctly is recommended.



6 F	lectr	ical (Com	ents	
Serv	NP	NI	Rev	Observation	ns:
X				• () <mark>AFCI</mark> : Mo	odern electrical codes require branch circuits at bedrooms and
			I	— certain other	er areas of
				the house, to	to be AFCI protected. The electrical code at the time this house
				was built ma	ay not have
				required AF	CI protection at these circuits. consult a qualified electrician.



1681 Medallion Court, Mississauga, Ontario


Heating

1. Heating

Х

Type: Gas Forced Air

2. Burner Chamber Comments



• ()Annual preventive maintenance is recommended.

• ()The furnace is original and or aged with the home and approaching the end of it's life cycle. Recommend budgeting for new furnace. Recommend HIP program. Home insurance plus from your local HVAC technician. Contact an HVAC tech to further evaluate and assess. Budget for new



()Annual preventive maintenance is recommended.




()Annual preventive maintenance is recommended.

3. Exhaust Venting Conditions



• ()Exhaust venting is in good condition at time of inspection unless noted.



()Annual preventive maintenance is recommended.




()Annual preventive maintenance is recommended.

Page 29 of 47

4. Humidifier Comments

Observations: A humidifying system is present on the furnace. As per the Inspection Agreement, humidifiers are beyond the scope of this inspection.

5. Air Filter Condition



Observations:

• ()Recommend cleaning or changing on a monthly basis to ensure life of furnace or follow recommended manufacture instructions of unit or filter .Installing of the filter in the correct direction is important.



()Recommend cleaning or changing on a monthly basis to ensure life of furnace or follow recommended manufacture instructions of unit or filter .Installing of the filter in the correct direction is important.

6. Thermostat Condition

Serv	NP	NI	Rev	None	Located at the dining room
x					Observations:

Observations: • ()Thermostat is in working order at time of inspection.



()Thermostat is in working order at time of inspection.

7. Distribution Ducting Condition	
Serv NP NI Rev None Type: Ducts and Registers	
 X Observations: ()Distribution of system is in good working order at time of inspection unle 	ess
noted.	,00
8. Gas shut off valves	
Serv NP NI Rev None Observations:	
X • ()Present at time of inspection in visible areas only.	
9. Heating Comments	
Serv NP NI Rev None Observations:	
X ()Automatic safety controls not tested	
• ()The furnace room should be free of all combustible materials at all times for safety. Installing carbon and smoke detectors in the entire home is needed. Carbon and smoke detector are to be tested semi annual and or	
yearly and replaced every five to 10 years according to the fire safety division of the township.	ION
It is recommended to research current bylaws within your township.	
It is recommended to have a Radon monitor in the home.	
10. HRV	
Serv NP NI Rev None	
11. Oil Tank	
Serv NP NI Rev None	

Air Conditioning

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Air Conditioning Comments

	Serv	NP	NI	Rev	N
ſ	Х				

Type: Split System

Observations:

• ()Air condition is working at time of inspection unless noted.



()Air condition is working at time of inspection unless noted.



()Air condition is working at time of inspection unless noted.

nch By Inch Inspections	1681 Medallion Court, Mississauga, Onta
10	latar Haatar
	/ater Heater
1. Water Heater	
The water heater is lo 50 gallon unit. • Age	ocated in the basement beside the furnace and is 40 or ed
2. Supply lines Condition	
X X X Materials: Copper Observations: • ()Good at time of ins	spection in visible areas only, unless noted.
3. Temperature Pressure Release Valve Co	nditions
during an release of h	aded with plastic drain pipe and may possible leak not water. Recommend copper piping. Always keep the e in case of a release from the hot water tank.
4. Combustion Chamber Conditions	
X NP NI Rev None Observations: • ()Unit is in good wor	rking order at time of inspection unless noted.
5. Flue Venting Conditions	
X NP NI Rev None Materials: Metal Observations:	at time of inspection unless noted.
6. Water Heater Comments	
release valve, if distu	e kept away from water heater as the high pressure rbed, can cause scalding. I not to store items near the hot water and furnace area s entry.
RHEEM MANUFACTURING CO. WATER HEATER DIVISION MONTGOMERY 1 SER D606J06763 42.4 GPH/160 LPH 2 GAS/GAZ: NAT Pa) 5 kPa) / 5 "w.c. (1.2 kPa) 5 kPa) / 5 "w.c. (1.2 kPa) 2 LINJECTEUR: # 30 221.10.1a / CSA 4.1a - 2004	

()It is recommended not to store items near the hot water and furnace area for safety and access entry. ()Children should be kept away from water heater as the high pressure release valve, if disturbed, can cause scalding.

Х

Other Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. Floor Condition
Image: Servine NP NI Revine Observations: X Image: Observation Observation Invisible areas only. Image: Observati
()Dry at time of inspection in visible areas only.
2. Wall Condition
Serv NP NI Rev None Observations:

Observations:
 ()Dry at the time of the inspection unless noted.
 ()Minor cosmetic concerns can occur at anytime by someone dropping,scratching, something or placing something on the wall. It is considered a minor cosmetic issue and not within the scope of this inspection as it focuses on basic structure and major systems only unless otherwise noted.

• ()Storage blocking in walls at time of inspection.

1681 Medallion Court, Mississauga, Ontario

Inch By Inch Inspections



()Dry at the time of the inspection unless noted.



()Dry at the time of the inspection unless noted.

3. Ceiling Conditions

Serv	NP	NI	Rev	None
Х				


Observations: • ()Dry at the time of the inspection in visible areas only unless noted.



()Dry at the time of the inspection in visible areas ()Dry at the time of the inspection in visible areas only unless noted.



only unless noted.




()Dry at the time of the inspection in visible areas ()Dry at the time of the inspection in visible areas only unless noted.



only unless noted.

4. Door Conditions



Observations: • ()Good at time of inspection unless noted.

5. Window Condition



None **Observations:**

• ()Yearly cleaning of tracks, lubricating and windows is recommended to extend the life of the window.

6. Electrical Conditions


	Serv	NP	NI	Rev	_ N
X	Х				

None **Observations:**

• ()Electrical is in good order at time of inspection unless noted. Random electrical outlets were tested through the home during the inspection. Good at time of inspection. Consult a qualified contractor as needed.



as noted



12. Appliance or Appliances	
X NP NI Rev None (X) Observations: • ()Appliance testing and op Consult your realtor for deta	peration is not within the standards of practice.
appliances and other items consumer safety alert issue regarding well known notice recalls and consumer produ Consumer Product Safety (Internet site if recalls are a • ()Fridge • ()Stove • ()Dishwasher • ()Washer and Dryer • ()Microwave	Include the identification of, or research for, that may have been recalled or have had a ed about it. Any comments made in the report are es and are provided as a courtesy only. Product uct safety alerts are added almost daily by the Commission. We recommend visiting the following concern to you: www.cpsc.gov.
• ()Microwave	
	<image/>
()Fridge	()Fridge

()Stove



Page 38 of 47

Inch By Inch Inspections

1681 Medallion Court, Mississauga, Ontario




()Stove



()Dishwasher




()Washer and Dryer



()Dishwasher



()Washer and Dryer



Inch By Inch Inspections 1681 Medallion Court, Mississauga, Ontario Attic 1. Methods Used to Inspect How Inspected: Inspected attic at hatch at time of inspection. 2. Framing Condition Serv NP NI Rev None Style: Truss Х Observations: • ()Truss seem to be in good standing order at time of inspection in visible areas unless noted. 3. Sheathing Condition NI None NP Rev Serv Materials: Plywood Observations: Х • ()Dry at time of inspection in visible areas only. • Nail staining noted. Dry at time of inspection. Nail staining noted. Dry at time of inspection. 4. Evidence of leaking Serv NP NI Rev None Observations: • ()Dry at the time of the inspection in visible areas only unless noted. Х 5. Insulation Condition Serv NP NI Rev Materials: Blown in insulation • Fiberglass Х Observations: • R-32 approx.8" to 10" or greater. • ()Recommend to add insulation, consult a qualified contractor. 6. Ventilation Conditions Serv NP NI Rev None Style: Hooded Roof Vents • Soffit Vents Observations: Х () Air flow needs investigation to confirm good air flow, consult a qualified contractor. Exhaust venting for the bathroom has insulation missing. It is recommended to install insulation on the pipe to Consult a qualified contractor. Recommended baffles.



Exhaust venting for the bathroom has insulation missing. It is recommended to install insulation on the pipe to Consult a qualified contractor.


7. W	/indo	ow C	ondi	tions	
Son	ND	NI	Pov	Nono	

X	0011	 	1.01	110110
	Х			

8. Electrical Conditions

Serv	NP	NI	Rev	None
Х				

9. Distribution/Ducting Conditions



10. Attic Comments

-		-			
Serv	NP	NI	Rev	None	. (
Х					

Observations:

• ()Attic should be reviewed at least twice per year to ensure ventilation openings are clear and air flow is adequate and to ensure development of possible suspect microbial(mold) mould is kept in check.

• ()Recommend monitoring performance of roof through regular attic review. Water intrusion can occur at any time.

Additional Comments

	Serv	NP	NI	Rev	None	Observations
Г						UDSEIVALIONS

Х			
^			

• ()-pre-COMPONENTS OF A VISUAL PROPERTY INSPECTION Please read the following information carefully. If any additional clarification is required, please contact Inch by Inch Inspections Inc. as soon as possible. THE INSPECTION

The purpose of a visual property inspection is to investigate and disclose the condition of a specific property at the day of the inspection to prospective buyers. However, it is important to note that while a reasonable effort is made to disclose the current (e.g. time of inspection or season specific condition of a property, the property inspector is limited to inspecting what they are able to see. In other words, as the property inspection is not a forensic investigation, the property inspector is unable to inspect the conditions behind walls, underground etc, nor are they able to predict any water leaks that may have the potential to occur. The observations that take place during a property inspection are summarized in the inspection report. Kitec plumbing was used from 1995 to 2007. It is recommended to inspect all main drains hidden and under ground (weeping tile) with a camera system to assure free flow of water .Consult a qualified contractor.

THE REPORT

Upon the completion of a visual property inspection, the property inspector will summarize and detail the observations and any pertinent on-site discussions related to the property. Notably, the report will outline the main concerns regarding the property. If additional clarification is required, it is recommended that Inch by Inch Inspections Inc. be contacted immediately prior to waving the inspection condition. Additionally, it is important to note that a property inspection is comprised of both the written PDF report and verbal component. Both components also play an important role in educating a prospective buyer about a property. As such, it is recommended that the inspection report not be forwarded to banks or insurance companies, , as there is a potential for misinterpretation.

FINAL INSPECTION

We recommend that a final inspection (several if possible) be scheduled before the final closing date to check for any new concerns (e.g. water leaks or property damage) that may have occurred since the last inspection. It is important to note that the property inspector is not responsible for any events that occur on the property. As such, a final inspection is to be understood as a protective measure for you and your potential investment. Additionally, we recommend that the purchaser inquire about and request full disclosure from the property owner about permits, any structural or latent defects that are or could be potentially problematic. For example, foundation cracks, electrical issues, previous mold concerns, problems with plumbing or concerns over the structure of the property.

LIMITATIONS

As outlined above, as a property inspection is a visual assessment the inspector is limited to comment on what they are directly able to observe. Therefore, a property inspection is not to be understood as an environmental assessment,insurance policy (e.g. mould or asbestos) or as serving as a replacement for Plumbing,Building, Pest-Rodent inspectionOil tank etc or Electrical Code Inspections. Additionally,the inspector is unable to comment on the potential impact of Electrical Code Inspections.

Additionally, the inspector is unable to comment on the potential impact of Electrical Code Inspections. Additionally, the inspector is unable to comment on the potential impact of previous illegal activities that may have transpired on the property.

MOULD (Mold)

Mould inspectioin is not within the home inspection standards of practice. ASBESTOS

Please note, if you choose to purchase a property that was built before 1986, it is likely that builders and

contractors used asbestos containing items in the construction of the property. For example, asbestos was primarily in building product like drywall patching materials,insulationbrick,mortar, siding,glues,cladding. Insulation wrap around vents etc,vermiculite,vinyl flooring or various others. In the purchase of this property, you assume the risk of potential asbestos. Additionally,if you are concerned about asbestos, we recommend that you contact an environmental testing company and request their assistance.

COST ESTIMATES

Due to the variability in repair and/or improvement cost estimates, the inspection report does not

include this type of information. Licensed contractors would be able to assist and provide you with a personalized cost estimate.

If large tress noted on property, further investigation of plumbing drainage system is needed. Consult a qualified contractor.

Always get estimates and have all work completed by competent, licensed, insured, and bonded professional contractors. All repairs should strictly adhere to Manufactures Installation Specifications, National, Provincial, Local codes, and the Authority having Jurisdiction. All work should be completed, inspected and certified before you close escrow. We recommend that estimates/repairs be done during your inspection contingency period.

TITLE INSURANCE

We recommend that purchasers acquire Title Insurance to help protect them in the event of any title related.

(R)Regular upkeep and maintenance is needed to ensure the upkeep of the home. Monitor the grading and extend the downspout to 4 to 6 feet away from the house for proper drainage of water. It is recommend on your final visitation before the closing date to speak to the vendor (owner) to ask the operation of all appliances such as the stove,

dishwasher,fireplace,irrigation,washing machine,dryer etc..

Minor cracking to tiled floor can occur at anytime by someone dropping something or placing something heavy on floor. It is considered a minor cosmetic issue and not within the scope of this inspection as it focuses on basic structure and major systems only unless otherwise noted.

Unless otherwise indicated the inspector will not test for asbestos,lead,oil tank, paint,formaldehyde,molds,soil contamination an other environmental hazards. Speak to the seller for discloser.

Also ask the vendor to show you the operation of the thermostat and its functions.

Also a hygrometer is recommended to measure the humidity in the home. A dehumidifier is recommended in the home and to be placed in the basement and connect a direct drain. I recommend a 50 pint dehumidifier, refer to manufacture recommendations.

Maintaining between 35% to 45% humidity is ideal for health and the home. Exercising the fan during and half of an hour after each shower and bath is recommended to extract moisture out of the bathroom. Wiping of ceramic walls is recommended to help the bathroom after each shower.

If a water softner, filter, sunroom, automatic sprinkler system, fire sprinkler system, pond- waterfalls and or pool, hot tub, well, septic system is within the property, this is not within the home inspection scope, standards of practice, consult a qualified contractor.

Refer to city bylaws for renovations, permits, additions, grading, sheds,

patio,pools,ponds, decks, for location of items etc. The report summary is for info only. The entire report needs to be read. The report is for intended party only.

"Note: Just as no two home inspectors and no two reporting systems are alike, no two inspection reports, even if performed on the same property at the same time, are alike. This pre-listing inspection report was performed for my client, and or the home seller, with the cooperation and assistance of my client/home seller. It assumes full disclosure on the part of my client/home seller. My client may choose to share my report with others, but it was performed solely for my client. And although Inch By Inch Inspections Inc performs all inspections and writes all reports objectively without regard to the client's personal interests, additional fresh inspections, which of course would reveal and report matters differently, should be considered."

It was a pleasure meeting you. Thank you for allowing me to serve you. Tony Muscat Inch By Inch Inspections Inc. IAC,CHI,CMI,CT,CCI,CWI

info@inchbyinchinspections.com

www.inchbyinchinspections.com

416-826-7172 1-888-445-0737

Insurance Information

1. Insurance Information

| X |

Serv	NP	NI	Rev	None	Observations	••
					Observations).

- Observations:
 1. Age of Home: approx 50+
 2. Furnace Age: 2001
 3. AC Age: approx.2011
 4. Roof Age: New to Mid Life
 5. Water Heater Age: approx 2006
 6. Plumbing lines:Copper
 7. Electrical Panel: Breaker Panel Main.
 8. Electrical Panel Installation date: N/A
 9. Electrical Supply: 200 AMP Service
 10. Electrical Wiring: Copper

- 10. Electrical Wiring: Copper

Glossary

Term	Definition
ABS	Acronym for acrylonitrile butadiene styrene; rigid black plastic pipe used only for drain lines.
AFCI	Arc-fault circuit interrupter: A device intended to provide protection from the effects of arc faults by recognizing characteristics unique to arcing and by functioning to de-energize the circuit when an arc fault is detected.
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.