

5592 RIVERBOTTOM RD W Duncan, BC

\$1,489,900

The information contained has been obtained through sources deemed reliable but cannot be guaranteed as to its accuracy. Any and all information of special interest should be verified and obtained through independent verification.







Cell: 250.732.1863 Office: 250.748.7200 Email: adam@adamballrealty.ca **www.adamballrealty.ca** 472 Trans-Canada Hwy, Duncan, BC V9L 3R6





Price:	\$1,489,900
Zoning:	RC-3
Floor Space:	2,192 sq ft
3 Bay Garage:	953 sq ft
Property:	2.44 acres
MLS#	963745

5592 RIVERBOTTOM RD W Duncan, BC

One-of-a-kind, 2.44 acre, riverfront gem is a rare find, and it's nothing short of spectacular! Step inside the custom-built Norwegian V-groove log home, boasting 2,192 square feet with 2 beds and 2 baths. Enjoy soaring vaulted ceilings & natural light from the large windows, offering views of the river & private landscape. The open-concept living & dining areas feature a stunning rock fireplace with wood-burning insert & hardwood floors. Upstairs, a handy mezzanine office overlooks the living space, & the primary bedroom is a sanctuary with walk-in closet, jacuzzi tub, ensuite, & private deck.

Outside, adventure continues with a private pond, complete with dock & fire pit area. The lower field is perfect for picnics & family gatherings with cement fire pits & picnic tables. The low-bank, walk-on Cowichan River frontage offers endless fun for fishing, swimming, tubing, & wildlife watching.

The 3-bay garage is ideal for hobbyists, includes a mechanics pit and could be suited if desired.





5592 RIVERBOTTOM RD W Duncan, BC


Property Notes

Nowegian V-groove log home custom built New septic system 2024 Newer hot water tank Durable metal roofs on both home and garage New well pump and filtration system 2023 House equipped with 200 amp service 953 sq ft garage with 220-volt power Garage could be suited if wanted Large carport for additional covered parking Crawlspace fully redone, sealed, and insulated One of the best fishing spots on the Cowichan River First time for sale on the market Large pond with dock and fire pit Lower field can be used for family gatherings & camping Walk in riverfront - perfect for fishing, swimming and endless fun





5592 Riverbottom Rd W



Shown length and width dimensions are approximate.
Area sq.ft. is representative of the on-site measurements. (1" accuracy)



Figures, Calculations, and Representations are for indicative and promotional purpose only. VI Standard Real Estate Services Inc. will not be liable for any damages of any kind arising from the mis-use of this information.

	Fin. Sq.Ft.	UnFin. Sq.Ft.	Total Sq.Ft.
Upper Level	759	0	759
Main Level	1433	0	1433
Workshop/Detached Garage	0	953	953
Total	2192	953	3145







LAND TITLE OFFICE STATE OF TITLE CERTIFICATE

Certificate Number: STSR4012570

File Reference: 35161-2(b/o)

RIDGWAY & COMPANY - CORIENNA ALEXANDER #200 - 44 QUEENS ROAD DUNCAN BC V9L 2W4

A copy of this State of Title Certificate held by the land title office can be viewed for a period of one year at <u>https://apps.ltsa.ca/cert</u> (access code 788531).

I certify this to be an accurate reproduction of title number CB1339453 at 12:27 this 31st day of May, 2024.

REGISTRAR OF LAND TITLES



Land Title District Land Title Office	VICTORIA VICTORIA
Title Number From Title Number	CB1339453 CA9603903
Application Received	2024-05-29
Application Entered	2024-05-31
Registered Owner in Fee Simple Registered Owner/Mailing Address:	INA ELAINE CLINE, RETIRED 5592 RIVERBOTTOM ROAD WEST DUNCAN, BC V9L 6J5

Taxation Authority

Nanaimo/Cowichan Assessment Area

LAND TITLE OFFICE STATE OF TITLE CERTIFICATE Certificate Number: STSR4012570			
Description of Land Parcel Identifier: Legal Description: PARCEL D (DD 36065I) OF SECTIO PART IN PLAN 13329	000-006-076 DN 7, RANGES 1 AND 2, SAHTLAM DISTRICT, EXCEPT		
Legal Notations RE CLAUSES (E) AND (F) OF SECTION 23(1) LTA, SEE DD3271 OS FILED 19.02.1976			
Charges, Liens and Interests Nature: Registration Number: Registered Owner: Remarks:	EXCEPTIONS AND RESERVATIONS M76300 ESQUIMALT AND NANAIMO RAILWAY COMPANY INTER ALIA AFB. 9.693.7434A SECTION 172 (3) FOR ACTUAL DATE AND TIME OF REGISTRATION SEE ORIGINAL GRANT FROM E & N RAILWAY COMPANY		
Duplicate Indefeasible Title	NONE OUTSTANDING		
Transfers	NONE		
Pending Applications	NONE		

This certificate is to be read subject to the provisions of section 23(2) of the Land Title Act(R.S.B.C. 1996 Chapter 250) and may be affected by sections 50 and 55-58 of the Land Act (R.S.B.C. 1996 Chapter 245).

PARCEL IDENTIFIER (PID): 000-006-076 SHORT LEGAL DESCRIPTION: U/SAHTLAM//1///7////D MARG:PC D (DD 360651) - REM* TAXATION AUTHORITY: 1 Nanaimo/Cowichan Assessment Area FULL LEGAL DESCRIPTION: CURRENT PARCEL D (DD 360651) OF SECTION 7, RANGES 1 AND 2, SAHTLAM DISTRICT, EXCEPT PART IN PLAN 13329 MISCELLANEOUS NOTES: KP 494 3487 PP -3271 OS (IMAGED, INCLUDING PLAN)-ROAD GAZETTE DATED 5TH FEBRUARY 1976, PAGE 139 FOR 0.06 ACRE PORTION OF RIVERBOTTOM ROAD IN PARCEL D. -360651 (IMAGED) DOCUMENT, DESCRIPTION AND PLAN -ALIVE AS TO PART OF PCL D WITHIN RANGE 2 SAHTLAM ASSOCIATED PLAN NUMBERS: SUBDIVISION PLAN VIP13329 POSTING PLAN VIP3487PP

AFB/IFB: MN: Y PE: 0 SL: 1 TI: 1




No one knows & laves your home like you do! Maybe there's a great park just up the road. Perhaps you have great neighbours. Maybe your home is eco-friendly constructed. There are many wonderful things about your home that you, as the owner, are aware of but may not be obvious to a prospective buyer. Please take a moment and consider the top 10 things that make your home a great place to live!

TOP 10 REASONS IT'S GREAT TO LIVE AT:

5592 RIVERBOTTOM RD W Address Private riverFront retreat 1 2 Tons of outdoor adventures at your doorstep 3 Huge 3 bay garage 4 Custom loghome with metal 5 roof Great neighbours - unique "micro community" 6 Fish, boat, tube From your own yard 7 15 mins to town (Duncan & Lake Courchan) 8 Sunny useable land 9 Beautiful wildlife 10 Quiet, peaceful








ADAM BALL Re/Max Island Properties DUNCAN P: +1250-732-1863 adam@adamballrealty.ca www.adamballrealty.ca

GOOD MOVE.





5592 RIVERBOTTOM RD W Rural BC V9L 6J5

PID	000)-006-076			Lega	ll Description	PARCEL D (DD 36065I) OF SECTION 7, RANGES 1 AND 2, SAHTLAM DISTRICT, EXCEPT PART IN PLAN 13329
Zoning	RC-	- <mark>3</mark> - River Corridor	3 Zone		Plan		NO_PLAN
					Com	munity Plans(s)	OCP: Land Use: River Corridor, not in ALR
Floor Area	1924 Ft ²	Max Elevation	84.31 m	Year Built	1978	Transit Score	-
Lot Size	2.44 acres	Min Elevation	67.51 m	Bedrooms	3	Walk Score	3 / Car-Dependent
Dimensions	-	Annual Taxes	\$3,458.00	Bathrooms	2	Structure	2 ACRES OR MORE (SINGLE FAMILY DWELLING, DUPLEX)

MLS HISTORY

MLS history not available

APPRECIATION

	Date	(\$)	% Change
Assessment	2024	\$929,000	30.48 %
Sales History	22/12/2021	\$712,000	71199900.00 %
	15/08/1983	\$1	-100.00 %
	15/06/1978	\$35,500	

SCHOOL DISTRICT

	Nearest Elementary	Nearest Secondary
Catchment	Tansor	Cowichan
District	SD 79	SD 79
Grades	K - 7	10 - 12

DEVELOPMENT APPLICATIONS

No records found for this parcel

AS:	CEC		NI	т
AD:	SES	SIVI	N	

	2023	2024	% Change
Building	\$390,000	\$275,000	-29.49 %
Land	\$509,000	\$654,000	28.49 %
Total	\$899,000	\$929,000	3.34 %

The enclosed information, while deemed to be correct, is not guaranteed.



Public Records Full Property Report

Property Identification & Legal Description

Address: Jurisdiction:	5592 RIVERBOTTOM RD W DUNCAN BO Duncan Rural (766)	C V9L 635
Roll No:	3503180	Assessment Area: 4
PID No: Neighbourhood:	000-006-076 North of Cowichan River	MHR No:
Legal Unique ID: Legal Description:	A00000RN8R PARCEL D, SECTION 7, RANGE 1, SAH	FLAM LAND DISTRICT, EXCEPT PLAN 13329, (DD 36065I), & OF RGE 2

2023 Municipal Taxes

Gross Taxes: \$3,458

2024 Assessed Values

VALUATION:

		Land	Improve	Total
	Value:	\$654,000	\$275,000	\$929,000
GENERAL:				
		Land	Improve	Total
	Gross Value:	\$654,000	\$275,000	\$929,000
	Exempt Value:	\$0	\$0	\$0
	Net Value:	\$654,000	\$275,000	\$929,000
SCHOOL:				
		Land	Improve	Total
	Gross Value:	\$654,000	\$275,000	\$929,000
	Exempt Value:	\$0	\$0	\$0
	Net Value:	\$654,000	\$275,000	\$929,000
BC TRANSIT:				
		Land	Improve	Total
	Gross Value:	\$0	\$0	\$0
	Exempt Value:	\$0	\$0	\$0
	Net Value:	\$0	\$0	\$0

Last Three Sales Per BCA

Conveyance Date	Price	Document No	Conveyance Type
2021-12-22	\$712,000	CA9603903	Reject - Not Suitable for Sales Analysis
1978-06-15	\$35,500	G56375	Improved Single Property Transaction
1976-04-15	\$26,000	E45198	Improved Single Property Transaction

Other Property Information


Lot SqFt: Lot Acres:	106,286 2.44	Lot Width: Lot Depth:	
Tenure:	Crown-Granted	Actual Use:	2 Acres Or More (Single Family Dwelling, Duplex)
School District: Vacant Flag: BC Transit Flag: Farm No:	Cowichan Valley No No	Manual Class: Reg District: Reg Hosp Dist: Mgd Forest No:	1.5 STÝ SFD - After 1960 - Standard Cowichan Valley Cowichan Valley
DB Last Modified:	2024-01-01	Rec Last Modified:	2024-01-01

Assessment & Tax History

Year	Assessed Value	Gross Taxes
2023	\$899,000	\$3,458
2022	\$812,000	\$3,384
2021	\$712,000	\$3,837
2020	\$663,000	\$3,767
2019	\$652,000	\$3,657

2018	\$568,000	\$3,344
2017	\$484,000	\$3,098
2016	\$474,000	\$3,278
2015	\$454,000	\$3,201
2014	\$455,000	\$3,155
2013	\$457,000	\$3,069
2012	\$465,000	\$2,934
2011	\$467,000	\$2,849
2010	\$448,000	\$2,671
2009	\$454,000	\$2,420
2008	\$462,000	\$2,403
2007	\$462,000	\$2,617
2006	\$356,000	\$2,330
2005	\$315,000	\$2,196
2004	\$243,000	\$1,908
2003	\$234,200	\$1,920
2002	\$232,700	\$1,887
2001	\$229,800	\$1,839

Print



Questions about this property assessment? Visit our Property assessment FAQ (https://info.bcassessment.ca/ faq) or Contact us (/property/contact) if you have questions.

Visit our BC Assessment interactive market trends maps (http://bcagis.maps.arcgis.com/apps/MapSeries/

index.html?appid=ba3d56fb4c144727896b25989bdf00d2) for assessed value changes in your area, and our Property tax page (https://info.bcassessment.ca/propertytax) to learn what your assessment value change means for your property taxes.

Find out more about BC Assessment's Data Services (https://info.bcassessment.ca/services-and-products/ Pages/Buy-and-Exchange-Data.aspx)

Property information	
Are the property details cor	rect?
Year built	1978
Description	1.5 STY house - Standard
Bedrooms	3
Baths	2
Carports	С
Garages	G
Land size	2.44 Acres
First floor area	1,380
Second floor area	544
Basement finish area	
Strata area	
Building storeys	2
Gross leasable area	
Net leasable area	
No.of apartment units	
Legal description and parcel	ID
DADCEL D SECTION 7 DANCE	

PARCEL D, SECTION 7, RANGE 1, SAHTLAM LAND DISTRICT, EXCEPT PLAN 13329, (DD 360651), & OF RGE 2

PID: 000-006-076

Sales history (last 3 full calendar years)


No sales history for the last 3 full calendar years


	BUILDING	INSPECTION RECORD		
BUILDING PERMIT	F-436-	.87 DATE	October 26, 19	87
CIVIC ADDRESS	5592 Riverbottom	Road ZONE	R-2	
DISTRICT	Sahtlam District	DISTRICT LOT	SECTION	7
RANGE	2 PLAN	13329 BLOCK	LOT	Pcl D.
PLACEMENT OF	Reside	ential Carport	_	
OWNER	Greg F	lanbury	PHONE	
BUILDER		Same	PHONE	Same


Insp	ection	Date Complet	ed	Not Approv. Date	Corrected Date	Insp.
1.	Footing, Forms (Prior to pouring concrete)	Oct 27/	81			DK
2.	Foundations Forms					
3.	Backfill & Perimeter Drain					
3(a)	Water/Sewer Hook-Up	-				
4.	Framing X	Nou lo	87-			R
5.	Plumbing					
6.	Insulation					
7.	Fireplace					
7(a)	Chimney Corbel (Prior to Facing)					
8.	Miscellaneous					
9.	Final Inspection PRIOR TO OCCUPANCY					

COMMENTS * (2) Wot melading trusses.

Permission has been granted Permission has been granted placement of	COWICHAN VALLEY REGIONAL DISTRICT BUILDING PERMIT	Residential Carport	AT (address)	•••••	Greg Hanbury ADDRESS. R.R. J2. Duncan, 3.C.	Same Same	JLARS This is to certify that BUILDING PERMIT NO. And been ISSUED for the above noted building. Permit fee of \$.42.00 has been received by 0ctober 26, 1987 Building Inspector.	This Permit confirms that the Regional District has reviewed Plans and the Application Form in respect of the Support Building persuant to Regional District Building By-Law No. 143, 1974. The Permit is not a Warranty that the Subject Building will comply with all Regional neut Provincial Regulations. Governing Building Construction nor that it is without Defect.
	ICHAN V	Residenti	5592. Rfye D/LSEC 7		Greg Nanbury	Same	o certify that BUILDIN fee of \$4200 October 261987	







DISTRICT Sahtlam	DISTRICT L	OT		SECTION	7
RANGE PLAN	13329 P	art of Pan BLOCK	rcel D	(DD 36065 I LOT	:)
PLACEMENT OF Single Family 1			_		
OWNER Mr. & Mrs. G. Hanbury			РНО	NE	
BUILDER			РНО	NE Same	
Inspection	Date Completed	Not Ap Dat	-	Corrected Date	Ins
 Footing, Forms (Prior to pouring concrete) 					
2. Foundation Forms					
3. Backfill & Perimeter Drain					
4. Framing INT. E. Rodf F. RAM	Nov 2/83				T
5. Plumbing	FLOOR FC3 3/84 Au 17 24	See be	low		RE
6. Insulation SOBSTANTING COMPLE	1 a alad			-	E
7. Fireplace	Fel: -5 83				A
8. Miscellaneous					
9. Final Inspection PRIOR TO OCCUPANCY	July 12/85	Seela	chefis	heet.	4
9. Final Inspection PRIOR TO OCCUPANCY COMMENTS FUB \$184 A FUN TUCK OUCL BUVING ROOM SIGG MILHANGURY 2- D Roley of Hom & Pawaday tob and would after showen. @ Frontide :	IN TROBLOMS	. ADUISER) To (JSP. (CORRET C	(soli toli

COWICHAN VALLEY REGIONAL DISTRICT.

BUILDING	INSPECTION	RECORD.
----------	------------	---------


BUILDING PERMIT NO. F/217/77	DATE June 24, 1977
CIVIC ADDRESS Riverbottom Road	ZONE R-2
Cabtlan	RICT LOT SECTION 7
	Part of Parcel D (DD 36065 I)
PLACEMENT OF single family dwelling (log house and garage)
OWNER Mr. & Mrs. G. Hanbury	PHONE
BUILDER self	PHONE
Inspection.	Date Not Approv. Corrected Insp. Completed Date Date
1. Footing, Forms (Prior to pouring contrete OCT 19 2. Foundation Forms	178 Quy 4/77
2. Foundation Forms Nov. 94/28 9. M.c.	3. aug. 26/7 g.74
3. Backfill & Permeter Drain	
4. Framing	Cet. 19/18 2.718.
5. Plumbing and Insulation	NA. NA
6. Fireplace	NG. NA.
7. Miscellaneous	
8. Final Inspection PRIOR TO OCCUPANCY	


COMMENTS


Surgeles (CX. april 10/75 273.8.

COWICHAN VALLEY REGIONAL DISTRICT BUILDING PERMIT Permission has been arouted for the construction or BUILDING PERMIT BUILDING INSPECTOR	rs. Creg Hanbury	AT (address)	ELECTORAL AREA	Nrs. G. Hambury ADDRESS6253 Fairview Way, Duncan, A.C.	ADDRESS	JLARS	Building Inspector.	217
COWICH/	placement of fix. & Mrs. Greg Hanbury	AT (address)	DISTRICTSahtlam	OWNER & Nrs.	BUILDER 3e1£	PARTICULARS	June 24, 1977.	Nº 771









HD Horne Sprayfoam & Insulation Ltd.

PO Box 37098 Victoria RPO Millstream BC V9B 0E8 +1 2508824629 HDsprayfoam@gmail.com GST/HST Registration No.: 735098071RT0001



INVOICE

_

BILL TO Ina Cline 5592 Riverbottom Rd W Duncan BC			INVOICE DATE TERMS	1711 22/08/2023 Due on receipt
		QTY	RATE	AMOUNT
Complete Crawlspace Remediation Insulation services Supply and install heavy duty 15 Mil ground sea earth throughout the crawlspace ensure a cons throughout		1	15,000.00	15,000.00
Ensure crawlspace is dry and there is no water No insulation existing. Supply and install R20 ck polyurethane foam to all exterior walls, headers crawlspace 800sq ft. Clean BC Income Qualified Rebate (60%) Note: maximum rebate value allowed is \$5,500 Code: 60-7ec9c51d	osed cell spray applied rigid and footings throughout	1	-5,500.00	-5,500.00
By booking our services you agree to our terms and con www.hdsprayinsulation.com. Insulation products and ser Horne have a 1 year warranty. Any deviation from above specifications involving extra upon verbal orders, and become an extra charge.	rvices provided by HD	SUBTOTAL GST @ 5% TOTAL		9,500.00 750.00 10,250.00
Deposits not needed but payment is due upon completion receive 2% interest compounded monthly beginning at du terms and conditions. Homeowners/Builders are responsible for ensuring. • The work area is prepared, accessible and free of debr	ay 30 along with other	BALANCE DUE		\$10,250.00
No live rodents are actively living in the work area. SPRAYFOAM ADVISORY: *Not applicable to blown/batt insulation* Occupants and pets must vacate premises during apple All other trades/persons without PPE must vacate the application and cannot re-enter until sprayfoam applicati Only our trained employees are permitted in the work 2 TAX SUMMARY	building during on is complete.			
	RATE		TAX	NET
	GST#73	oyal BL# 13167 15098071RT0001 1age 1 of 1	0.00	15,000.00

HD Horne Sprayfoam & Insulation Ltd.

PO Box 37098 Victoria RPO Millstream BC V9B 0E8 +1 2508824629 HDsprayfoam@gmail.com GST/HST Registration No.: 735098071RT0001



INVOICE BILL TO			IN	VOICE	1710
Ina Cline 5592 Riverbottom Rd W Duncan BC			DA	RMS	22/08/2023 Due on receipt
		. 0	YTC	RATE	AMOUNT
Pest and Rodent Services Set traps for rodents, followed by 4 visits to inspect needed until no more visible signs of rodents	traps and reset as		1	3,600.00	3,600.00
Assess entry points of rodents and make plan of act	ion to close the acce	ss			
Complete removal of deteriorated insulation and deb	ris from crawlspace				
1 x 20 yard disposal bin & rural delivery and pickup	fees				
Landfill fees					
Clean BC Income Qualified Rebate (60%) Note: maximum rebate value allowed is \$5,500 Code: 60-7ec9c51d			1	-800.00	-800.00
By booking our services you agree to our terms and condition www.hdsprayinsulation.com. Insulation products and services		SUBTOTAL			2,800.00
Home have a 1 year warranty Any deviation from above specifications involving extra costs	will be executed	GST @ 5% TOTAL			180.00 2,980.00
upon verbal orders, and become an extra charge. Deposits not needed but payment is due upon completion. Ov receive 2% interest compounded monthly beginning at day 30 terms and conditions.		BALANCE DUE			\$2,980.00
Homeowners/Builders are responsible for ensuring: • The work area is prepared, accessible and free of debris and • No live rodents are actively living in the work area.	clutter.				
SPRAYFOAM ADVISORY: "Not applicable to blown/batt insulation" • Occupants and pets must vacate premises during application • All other trades/persons without PPE must vacate the buildin application and cannot re-enter until sprayfoam application is o • Only our trained employees are permitted in the work zone. TAX SUMMARY	g during				
	RATE		TA	×	NET
GS	T @ 5%		180.0	0	3,600.00
		Royal BL# 13/167 735098071RT0001 Page 1 of 1			


592 West Riverbottom Road Duncan, British Columbia V9LPaid50-748-2452Jul 22, 2023


vice callout + 3 hrs overtime

tere was a leak on a 2" abs drain line in the crawlspace. It was a cracked fitting. It has contaminated the crawlspace to w unsafe to enter. I was able to access the leak through the floor. Repaired. There was some concern that this could be rat 1 was a stress fracture on a 2" abs coupling. It was not rat related.

Vhile I was opening the floor up I bumped corroded brass pex fitting. It was so soft it snapped in half. Repaired.

QTY.	UNIT PRICE	TOTA
3	\$300.00	\$900.
cellaneous		
aterials		
QTY.	UNIT PRICE	ΤΟΤΑ
1	\$65.00	\$65.
vice callout Chris + helper		
pipe laundry sink drain and waterlines into the	e sink cabinet	
ean wall cavities. Rat proof wall cavities.		
place drywall. Re-enforce flooring. Replace s	ubfloor	
stall laundry sink. New shut off valves, drain a		
stall clean out fitting at the laundry sink, auger	uram. Cleared.	
stall washer/dryer.		
QTY.	UNIT PRICE	ΤΟΤΑ
4.5	\$250.00	\$1,125.
cellaneous		
aterials		
QTY.	UNIT PRICE	ΤΟΤΑ
btotal 1	\$275.00	\$2,375:
t (5.0%)		\$118.
tal		\$2,483.
id voice balance		- \$2,483.
ank you for your business. Please contact us w	with any questions regarding this invoice	\$0.
and you for your busiless. I lease contact us v	any questions regarding this involce.	
ST 846433712RT0001		
Contact Chris Bohmer Plumbing & Gas	Teterit Ditt C.L. L. MOC 100	
	venue, Ladysmith, British Columbia V9G 1N9	
250-740-7474 c.bohmer75@gmail.com		
Created with getjobber.com		





Copper Canyon Plumbing 5603 Riverbottan Rd. Westare July Duncan BC 005228 22 2022 V9L 6H9 (250)715-5047 Nº DE COMMANDE ORDER NO. VENDU À SOLD TO lee Cline ADRESSE RZ. West Riverbotto EXPÉDIER À SHIP TO ADRESSE DATE D'EXPÉDITION SHIPPING DATE ACHETEUR BUYER VENDU PAR CONDITIONS TERMS VIA SOLD BY MONTANT QUANTITÉ PRIX DESCRIPTION 1 2 2 Insta Jet pump, Filters Pressure 3 4 and 5 Materials 20 247 6 450 28 7 Labor 8 9 10 3 11 12 13 TPS/GST 14 TVH/HST TVP/PST 15 P 2945 TOTAL 16 XX SIGNATURE sures 528 FORMULAIRE DE VENTE = SALES ORDER =



Home Depot Canada Inc. Store 7272 DUNCAN - 7272 1 - 2980 Drinkwater Road Duncan, British Columbia V9L 6C6 (250) 737 2360 To follow up on the status of this order please send us an SMS at 84322 (standard rates may apply) or call us: Appliances: 18007592054 Kitchens or Flooring projects: 18447705328 x2422

Page 1 of 3 Sales Person: KXB0851 03.03.2023 15:43:45

ORDER NO. 606944759

Last Name: HANBURY Address 5592 W R Province BC	First Name: G	Phone (250) 748 2452
Address 5592 W R	IVERBOTTOM RD	City DUNCAN
Province BC	Postal Code V9L 6H9	Job Desc. take with
	MERCHANDISE AND SERVICE CUMMAA BY	

MERCHANDISE AND SERVICE SUMMARY

Qty	UoM	Tax	Price Each	Extension
			and a second	CALOHOIOII
1	.00 EA	Y	\$515.00	\$515.00
			4010.00	
	010000000000000000000000000000000000000	Contractor in the	COLUMN TO THE OWNER	\$2.50
-		1.00 EA		END 0

	PRE-DISCOUNT TOTAL	
	TOTAL DISCOUNT	\$517.50 \$0.00
	PRE-TAX TOTAL	\$517.50
	GST R135772911	\$25.88
	QST 1021794119	N/A
	PST	\$36.23
	HST	N/A
END OF ORDER NO. 606944759	TOTAL	\$579.61

FOR MERCHANDISE PICK UP PROCEED TO SERVICE DESK AREA



ORDER NO. 606944759

98010138259941

SOUTH FIREPLAC Tel: (250) 746 - 0123		INSPEC	FUEL 2398 CTION FORM
www.southislandfireplaces.com	sales@southlalandfireplaces.com		
ADDRESS -	POSTAL CODE		AUG 25/17
5592 WEST R	INABOTTON RD	V9L-649	
DUN CAN	[P3	10NE 250-748-2452	POLICY#
LOCATION OF UNIT WITHIN D	WELLING	Appliance Type: WCD	D INSKERT
Make PACIFIC ENERGY	Model NJEe 2	Serial #	
	CACSA DULC	WARNOCK HERS	SEY D'OTHER EAL
HEATING UNIT Manufacture	Approved Classeness (Corolisted and	A	
	r Approved Clearances (See Label on Back	Comer	AHE IN INCHES Mantie (Insert) Measured From Insert Top Shelf
Headh Deard	Hearth Side 81/	Hearth Rear	16"
1811	. Ø.i	/	10
Hearth Front 1911	Back	Conver	Mantle (Insert) Measured From Insert Top Shelf
Hearth Front 1911	Hearth Skie 31 4	Hearth Rear	Do All Measurements YES NO
	rds burned per year? 1-14	Wood and Oil Other, specify:	
<u> <u> </u> <u> </u></u>	days per week Is the unit primary source	Primanu	
<u> </u>	g Code Requires a Stainless Steel Lin	source:	Elegnic
		NO Eactory Built Claes A Manufa	
Factory Built 650 Degree			
			Inside Building Outside Building
17	41 BY: PROFESSIONAL S	SWERE Date of last	cleaning: NEW UNBER
STOVEPIPE	1		
Single Wall Stovepipe Double Wall	Stove Pipe Manufacturer:	Does Stove Pipe Pass Through a Combustible Wall?	YES NO Length of Stove Pipe
Distance to wall: Construct	ion of Wall:	istance to Ceiling: Cons	truction of Celling
INSTALLATION Was the appliance installed by a heating Was the Chimney Installed by a heating			SOUTH ISUND FIME PURE LINGER - SAME
Does the stovepipe pass through a conc		NO YES Explain:	
Is protective shielding used around heat Does the unit share a chimney flue with a		YES Material, clearances etc.	
Does other appliance vent above or belo		YES Explain details: Below	
Has the installation, including chimney b	een inspected and		
approved by a fire department or buildin Smoke detector on the same floor as un		VES Name of Inspector: wide detector in the building?	AVES DINO
Fire extinguisher in the area of the unit?	DIVES DINO TYPE:	in the building r	
Where are ashes kept? METAC	CATAINIER_ How are ast	nes disposed of? 655 (D	E
Special Notes			

Aaron Watt	Please reference invoice number with e-trans			- all laster gool.	CLEANING INSPECTION INSTALLATION ESTIMATE FLUE FFLUE-LINER OIL FLUE PIPE FINSERT OIL PIPE CLEANOUT WOODSTOVE COOKSTOVE FIREPLACE WOOD FURNACE OIL FURNACE	NAME: Claure Cline. ADDRESS: SOD Reverbettom Pol.	250-715-0634 4504 Cowichan Lake Road, Duncan V9L 6J4 1safetysweepchimneyservice@gmail.com G.S.T. #R837214121	SAFE chimney service	SATV SWEEP	Mary a series of the
	SOLD TO VENDU A	£41.7 (24)	-710-8172	nd ices Ltd. P Rd cusp	SHIP TO EXPEDIER A ADDRESSE MIKES		hay 15 Me 9c1+d	2.		n
111	CUSTOMER'S OR	DER.	SOLD BY VENDU BAR	CON	AS DITIONS	FOB FAB		VIA		
	CUSTOMER'S ORC	2 CELATI		and it is not a supervised and it is supervised and the		and the second s				Taking .
NVOICE			le de la compañía	DESCRIPTION			PRICE PRIX		AMOUR	NT
INVOICE — FACTURE			l septric						\$325	
FACTUR			l septric wast				PRICE PRIX	UNITE UNITE 700		
FACTUR			l septic wast						\$3 <i>2</i> 5 \$ 329	
FACTUR									\$325 \$329 \$329 \$654 \$32.	

k lack ac Sweeps & Services River CHIMNEY SWEEP & GUTTERS DATE: SLAPT 23 NEXT DUE DATE: WORK PERFORMED 2 **Insert Flue** Fireplace Flue Pipes L 4 Smoke Shelf Stove Flue Furnace Flue Clean Out TLONX Misc. Amount Due \$_ DUNCAN 250-748-4011 blackiacksweep@hotmail.com BOTH FLUES DONE LAST SEPTEMBER. HAVEN'T USED WOODSTOVE

k lack ac Sweeps & Services Rive CHIMNEY SWEEP & GUTTERS DATE: SGPT 23 NEXT DUE DATE: WORK PERFORMED 2 **Insert Flue** Fireplace Flue L Pipes 4 **Smoke Shelf** Stove Flue Clean Out Furnace Flue TLONY Misc. Amount Due \$_ DUNCAN 250-748-4011 blackiacksweep@hotmail.com BOTH FLUES DONE LAST SEPTEMBER. HAVENT USED WOODSTOVE

Phone: 250-746-4277 SKSSE SKSSE ENVIRONMENTAL www.skseptics.ca • ska 5881 Howard Ave. Duna Customer INA (1) Address 5592 West Email	septics@shaw.ca can, BC V9L 3N7	Phone Work Cell Fax	748 de	-
Deposit of	DESCRIPTION OF WORK Fall new onsite wa 2,500,00 b Ted around Ap	y shequ	. 2	PRICE
COMMENTS: Payment Due Upo Signed	n Receipt • GST # R897529400		SUBTOTAL DEPOSIT GST PST TOTAL	920:01

island health Filing#: DC24/046	SEWERAGE SYSTEM LE Folio or PID#: 000 - 0		100000000000000000000000000000000000000	N ay 17, 2024
	est Riverbottom Road, D	and the second se	_ Date:	
Legal Description: Parcel	D,, Section 7, Range 1, Sahtlan	n District, L.D. Exce	pt Plan 133	29 (dd 360651) & of RGR 2
The construction of the prop	osed sewerage system on the abov	e property was com	pleted on: N	lay 16, 2024
This system was installed:				
By or under the supervis	ion* of a professional	_{Name:} n/a		Registration #:
	Vastewater Practitioner Installer	Name: Stewar	t Krumm	Registration #: OW0033
By the property Owner u		_{Name:} n/a		Registration#:
l am an "Authorized Person" the undersigned on this do	' as defined in the Sewerage Syste: sument certifies that:	m Regulation "BC R	eg. 326/2004	4." The signature and seal o

1. The Owner has been provided with:

A00

- A copy of the sewerage system plans and specifications as filed with the Health Authority;
- A maintenance plan for the sewerage system that is consistent with standard practice;
- · A copy of this Letter of Certification as filed with the Health Authority;
- The sewerage system has been constructed in accordance with standard practice as indicated in the Sewerage System Filing Form filed on (date) May 6, 2024 ;
- The sewerage system has been constructed substantially in accordance with the plans and specifications filed with the Health Authority;


4. The estimated daily domestic sewage flow through the sewerage system will be less than 22,700 liters;

5. If operated and maintained as set out in the maintenance plan, the sewerage system will not cause or contribute to a health hazard.

* Where the authorized person is a professional, "supervision" means conducting field reviews of the construction of the above system that the professional In his or her professional discretion considers necessary to ascertain whether the construction substantiality complies with the plans and specifications filed with the Health Authority.

Appended to this document is a plan of the sewerage system as it was built and a copy of the maintenance plan.

Name (please print): Stewart Krumm		Health Authority Use Only
Signature: MASTEWART G. KRUMM PL IN OW0033 OW0033	rson's Seal RECEIVED MAY 1 7 2024	ISLAND HEACTH FILING ACCEPTED MAY 17 2024 This filing Does Not Consultate Approved for Further Subdivision





Office: (250) 746-4277 Fax: (250) 746-4257

Email: skseptics@shaw.ca Web: www.skseptics.ca

> ISLAND HEALTH FILING ACCEPTED

MAY 17 2024

This filing Does Not Constitute Approval for Further Subdivision

5881 Howard Ave, Duncan B.C. V9L 3N7

Maintenance Plan for onsite wastewater system installed at 5592 West Riverbottom Road, Duncan

Prepared May 17, 2024

Owners: Ina Cline Site: 5592 Riverbottom Road Phone: 250 710 5363 Legal: Description: Parcel D, Section 7, Range 1, Sahtlam Land District, Except Plan 13329 (DD 360651) and of Range 2 Folio # 03503.180 PID: 000 - 006 - 076 GPS location: Latitude – 48.779765 Longitude – 123.791713

System Summary

3 Bedroom House (Residential only) Total Living Area allowed: 280m² (3014 ft²) Daily Design Flow rate (DDF): 1300 LPD (286 GPD) Expected Average Daily flows: 650 LPD (143 GPD) System: Type 1 Pressure distribution to a seepage bed Hydraulic Loading Rate chosen: 32 Area of infiltrative surface (AIS) = DDF/HLR = 41 LLR 170 1300 LPD/170 LLR = 7.65m in length, (25 feet) Min. discharge area length Rock bed area is 3m wide X 13.5m in length

Tanks

New 1000 Gallon two compartment septic tank with an effluent filter

New 600 Gallon one compartment pump tank

Maintenance Plan for Sewerage System installed at 5592 West Riverbottom Road, Duncan

Page 1 of 4

RECEIVED

MAY 1 7 2024

Rhombus Indoor outdoor alarm will be set on demand dose to pump approximately 27 Gallons per pump cycle. The audible and visual alarm is part of the panel.

Discharge area

All work to follow the Standard Practice Manual. All Pipe to be CSA approved Type 1 Pressurized to Seepage bed

Excavation for receiving area, mound sand and pea-gravel bed

Installer is to excavate into approximately 55cm of native soil, then place 45cm of C- 33 Sand.

Then Place 9" of clean drain rock, Then install 4 - 11/4" PVC lines, Orifice shields will cover 11/64

orifice, then rock will cover all PVC pipe, Filter cloth and then 7" of soil.

Rock Bed Size and Piping information

- 4 Laterals that are end fed run the length of rock bed
- Lateral spacing is 45cm from the outside edge
 - 60cm between laterals
- Orifice spacing is 76cm (30 inches) on the pipe
 - 11/64 orifice size
 - Orifice shields will cover the drilled holes
 - Lateral length is 13.5.m (45 feet)
- The manifold is 2 inch CSA PVC
- Flush-outs are installed at the end of each line with 2 45degree fittings
- Ball valves to control each lateral at the start of each line
- All flush-outs and valves for the discharge area have proper valve-boxes to cover them

in order to provide protection and later access

For answers to any questions of concerns please contact:

Stewart Krumm (250) 709-4497 skseptics@shaw.ca



Maintenance Plan for Sewerage System installed at 5592 West Riverbottom Road, Duncan

Page 2 of 4

ISLAND HEALTH FILING ACCEPTED

MAY 17 2026

This filing Does Not Constitute Approval for Further Subdivision

Planned Maintenance and Inspection to include the following checks once a year

Act in accordance to the Standard Practice Manual

- Confirm continued protection of the septic field and the tanks
- No structures or heavy traffic, ensure appropriate vegetation and landscaping, no

groundwater or surface flows that could interfere with proper operation of dispersal

field

- Check the security and safety of the tank accesses
- Confirm limited solids carry over to the filter compartment
- Check condition and proper operation of inlet and outlet tees
- Clean fats, oil and grease from the tees
- Inspect and clean the effluent filter at the outflow of the septic tank
- Measure to confirm that tank solids and sludge are under pump out requirements
- Recommend pump out only if required
- Flush lines and do a squirt test (squirt should be at least 2 feet with 11/64 holes in caps)
- Provide customer with a detailed document covering all components of the system and

a description of the maintenance provided

All components are on the attached Record Drawing for exact location

For answers to any questions or concerns please contact

Stewart Krumm


(250) 709-4497

skeptics@shaw.ca



Maintenance Plan for Sewerage System installed at 5592 West Riverbottom Road, Duncan

Page 3 of 4





Office: (250) 746-4277 Fax: (250) 746-4257 Email: skseptics@shaw.ca Web: www.skseptics.ca

5881 Howard Ave, Duncan B.C. V9L 3N7

Owner's Manual

Prepared May 17, 2024

Owner's Responsibilities

The new Sewerage System Regulations of (2005) require that an owner ensures the following:

- That the system be inspected and maintained in accordance with the maintenance plan included in this final package of documents. The frequency and scope of work are specified in the maintenance plan.
- That only Authorized Persons who are registered and certified as a Professional or a Registered Onsite Wastewater Practitioner construct, repair or maintain the sewerage system.
- That the owner maintains records of maintenance performed over the years.
- The owner does not misuse and neglect the system which will result in health hazards or risks to the environment.

Record Keeping

The owner must keep all records including Health Authority forms, design specifications, record drawings, maintenance plans and owner's manuals. Copies of these documents have been filed with the local Health Authority as required.

- SK Septics has complete documentation pertaining to the entire design and installation process of this sewerage system
- The owner must obtain the appropriate documentation from the maintenance provider as maintenance is performed on the system.



Owner's Manual for new onsite wastewater system installed at 5592 West Riverbottom Road. Page 1 of 7

Maintenance

The new (2005) Sewerage System Regulation requires owners to ensure their systems are maintained by authorized persons according to the maintenance plan provided. It is extremely important that regular maintenance and monitoring as specified in the maintenance plan.

Owners: Ina Cline Site: 5592 Riverbottom Road Phone: 250 710 5363 Legal: Description: Parcel D, Section 7, Range 1, Sahtlam Land District, Except Plan 13329 (DD 360651) and of Range 2 Folio # 03503.180 PID: 000 - 006 - 076 GPS location: Latitude – 48.779765 Longitude – 123.791713

System Summary

 3 Bedroom House (Residential only)

 Total Living Area allowed: 280m² (3014 ft²)

 Daily Design Flow rate (DDF): 1300 LPD (286 GPD)

 Expected Average Daily flows: 650 LPD (143 GPD)

 System: Type 1 Pressure distribution to a seepage bed

 Hydraulic Loading Rate chosen: 32

 Area of infiltrative surface (AIS) = DDF/HLR = 41

 LLR 170 1300 LPD/170 LLR = 7.65m in length, (25 feet) Min. discharge area length

 Rock bed area is 3m wide X 13.5m in length

Tanks

New 1000 Gallon two compartment septic tank with an effluent filter

New 600 Gallon one compartment pump tank

Rhombus Indoor outdoor alarm will be set on demand dose to pump approximately 27 Gallons per pump cycle. The audible and visual alarm is part of the panel.

Discharge area

All work to follow the Standard Practice Manual. All Pipe to be CSA approved Type 1 Pressurized to Seepage bed

MAY	1	7	2024
att	1	1	2024


Owner's Manual for new onsite wastewater system installed at 5592 West Riverbottom Road. Page 2 of 7

Excavation for receiving area, mound sand and pea-gravel bed

Installer is to excavate into approximately 55cm of native soil, then place 45cm of C- 33 Sand. Then Place 9" of clean drain rock, Then install 4 - 11/4" PVC lines, Orifice shields will cover 11/64 orifice, then rock will cover all PVC pipe, Filter cloth and then 7" of soil. Rock Bed Size and Piping information

- 4 Laterals that are end fed run the length of rock bed
- Lateral spacing is 45cm from the outside edge
 - 60cm between laterals
- Orifice spacing is 76cm (30 inches) on the pipe
 - o 11/64 orifice size
 - Orifice shields will cover the drilled holes
 - Lateral length is 13.5.m (45 feet)
- The manifold is 2 inch CSA PVC
- Flush-outs are installed at the end of each line with 2 45degree fittings
- Ball valves to control each lateral at the start of each line
- All flush-outs and valves for the discharge area have proper valve-boxes to cover them in order to provide protection and later access

For answers to any questions of concerns please contact: Stewart Krumm (250) 709-4497 <u>skseptics@shaw.ca</u>



Planned Maintenance and Inspection to include the following checks once a year

Act in accordance to the Standard Practice Manual

Confirm continued protection of the septic field and the tanks

REC	EIVED
ΜΑΥ	1 7 2024

Owner's Manual for new onsite wastewater system installed at 5592 West Riverbottom Road. Page 3 of 7

- No structures or heavy traffic, ensure appropriate vegetation and landscaping, no groundwater or surface flows that could interfere with proper operation of dispersal field
- Check the security and safety of the tank accesses
- Confirm limited solids carry over to the filter compartment
- Check condition and proper operation of inlet and outlet tees
- Clean fats, oil and grease from the tees
- Inspect and clean the effluent filter at the outflow of the septic tank
- Measure to confirm that tank solids and sludge are under pump out requirements
- Recommend pump out only if required
- Flush lines and do a squirt test (squirt should be at least 2 feet with 11/64 holes in caps)
- Provide customer with a detailed document covering all components of the system and a description of the maintenance provided
- All components are on the attached Record Drawing for exact location FILMG ACCEPTED

MAY 17 2026

For answers to any questions or concerns please contact Nation

Stewart Krumm (250) 709-4497

skeptics@shaw.ca

Must not overload the system

- Your onsite wastewater systems are designed for peak flow volume of 286 gallons per day of residential sewage. Average flows a month should not exceed 60% of the peak volume design flow which is approximately 172 gallons per day.
- The design flows are a conservative allowance for the expected flow under normal residential use of your 3 bedroom house.



Owner's Manual for new onsite wastewater system installed at 5592 West Riverbottom Road. Page 4 of 7

- Prolonged flows in excess of this design capacity will overload the system. This can cause premature failure of the system and can cause health hazards to humans and harm the environment. Health regulation violations and liability can result – with the responsibility on the homeowner.
- Although you are not expected to accurately determine and monitor these flows, you are advised to use a common sense approach to avoid overloading the system. If you make changes to the house or other buildings that will increase the sewage flows then the design must be reviewed and the system enlarged to accommodate the changes. Examples include water filtration systems, additional bedrooms or washrooms, starting Bed and Breakfast operations and other home based business with significant increases to the number of people using the system.
- Introducing high strength sewage (industrial/commercial/strong chemicals) will harm bacteria and severely reduce the treatment ability of the system with potential impacts to public health and the environment. Changes to the strength and characteristics of the sewage require immediate design modifications to accommodate the sewage input change.
- Adding water softener systems, in sink garbage disposal units, operating dark rooms and wine or beer making are examples of activities that will alter the sewage flow anticipated in the original design.
- See the Do and Do Not section for more information on how to avoid misuse of the system.

 BLAND HEALTH

 PILING ACCEPTED

Do and Do Not

Your sewerage system relies on treatment inside the septic tank and in the solid of the system, distribution field to reduce the harmful qualities of the wastewater. Longevity of the system, preventing health hazards and minimizing impacts on the environment depend on your proper use and maintenance of the system.

- Promoting bacteria growth by avoiding products and chemicals that will reduce CEIVEE eliminate bacteria growth
 MAY 17, 2024
- Minimizing non biodegradable materials, fats, oils and grease

Owner's Manual for new onsite wastewater system installed at 5592 West Riverbottom Road. Page 5 of 7

1444		
MAY	17	2024
		104035050
 		-

MAY 17 2024

- Not overloading the system beyond its capacity to treat the sewage
- Ensuring that regular maintenance is carried out

Tips to Ensure Proper Treatment and Longevity of the System for Puttons Not Co

IGLAND HEALTH FRING ACCEPTED


MAY 1 7 1924

MAY 17 2024

- Contact SK Septics before planting trees or excavating near the discharge area
- Avoid, reduce and control the use of disinfectants, bleach and anything that kills bacteria
- Do not use Drano or Liquid Plumber style products to clear clogged plumbing because they are very damaging to bacteria
- Do not put the following into the system: lubricating oils, greases, petroleum products, antifreeze, automotive fluids, chemical waste, toxins, paints, solvents, thinners, caustic cleaners, pesticides or herbicides
- Reduce and avoid where possible fats, oils and grease from food preparation because they are very difficult to break down, cause filters to clog and drastically shorten the life of the system by clogging sand and soil in the dispersal area
- > Use strategies to reduce like: collecting fat from fried foods, oil from deep fryers etc. and disposing of them in the garbage
- Do not allow non-biodegradable materials to enter the system because quicker buildup of solids will result in higher frequency of pump outs needed
- Do not allow bandages, strings, rags, cotton balls, coffee grinds, paper towels, condoms, disposable diapers, cigarette butts, plastics, metals, kitty litter, feminine products and other materials that do not compose easily
- Do not allow excessive amounts of hair and laundry lint to enter the system because it causes thickening and matting of the scum in the tank by entangling other solids and it can clog filters
- In-sink garbage disposal units increase the organic matter entering the system and should not be used unless the system has been designed and sized to accommodate.
- Do composting to limit organics from entering

Owner's Manual for new onsite wastewater system installed at 5592 West Riverbottom Road. Page 6 of 7

	ERAGE SYSTEM			D	3 # (OFFICE USE) $34/04$	6.	
INFORMATION		ALTERATION n/a	REPAIR		ENDMENT - OR	iginal fi	LING #:
	TAX ASSESSMENT ROLL 03503.180	#:		PID #	006 - 076		
	LEGAL DESCRIPTION (P	AN, LOT, DISTRICT	LOT, BLOCK NUMBERS):				
island health	Parcel D, Section 7,	Range 1, Sahtlan	Land District, Excep	t Plan13	329 (DD3606	51) And	of Range
	STREET (CIVIC) ADDRES				ату: Duncan		
INFORMATION	NAME OF LEGAL OWNER	:		0.0000	NG ADDRESS: 2 West Riv	erbott	om Roa
	PHONE:		CITY:	1	PROV:	POSTAL	CODE:
	250 710 536	3	Cowichan	Bay	BC	1	1N2
AUTHORIZED PERSON INFORMATION	NAME OF AUTHORIZED		REGISTRATION #: OW0033	1.201	B81 How		Δνο
	PHONE:	EMAIL:	0110000		PROV:		
	250 709 4497	10255	@shaw.ca	CITY: Dunca	BC	V9L	3N7
INFORMATION	SINGLE FAMILY DWE 3 Bedroom house THE DESIGN DAILY DOM	e, residential o		ew syst		ice exi	sting on
						100 -411	
SITE INFORMATION	DEPTH OF NATIVE SOIL TABLE OR RESTRICTIVE 150 plus	to seasonal high ' Layer (cm):	WATER INFORMATIO		TING THE TYPE, HED 🖬 YES		ND POROSI
SITE INFORMATION	TABLE OR RESTRICTIVE 150 plus GPS LOCATION OF SYSTE	Layer (cm): Em (decimal degrei	OF THE SOIL ES) LATITUDE: 48.76855	IS ATTACI	HED YES	23.876330	NO NO
DRINKING WATER	TABLE OR RESTRICTIVE 150 plus GPS LOCATION OF SYSTE HORIZONTAL ACCURACY	LAYER (cm): EM (DECIMAL DEGREI (m)_ ¹¹	OF THE SOIL ES) LATITUDE: 48.76855	IS ATTACI	HED TYES	23.876330	_
	TABLE OR RESTRICTIVE 150 plus GPS LOCATION OF SYSTE	Layer (cm): EM (decimal degrei (m) Stem be located li Ssional's report /	OF THE SOIL ES) LATITUDE: 48.76855 REC ESS THAN 30m FROM A V AND SPECIFY THE INTEN	IS ATTACK	HED YES	23.876330 DIFFEREN	NO NO
DRINKING WATER PROTECTION	TABLE OR RESTRICTIVE 150 plus GPS LOCATION OF SYSTH HORIZONTAL ACCURACY WILL THE SEWERAGE SY IF YES, ATTACH A PROFE	LAYER (cm): EM (DECIMAL DEGREI (m) STEM BE LOCATED LI SSIONAL'S REPORT / SEWERAGE SYSTEM	OF THE SOIL ES) LATITUDE: 48.76855 REC ESS THAN 30m FROM A V AND SPECIFY THE INTEN	IS ATTACK	HED YES LONGITUDE: 12 AL GPS I YES NO NINCE n/a 3 30 plus	23.876330 DIFFEREN	I NO ITIAL GPS
DRINKING WATER PROTECTION SYSTEM INFORMATION	TABLE OR RESTRICTIVE 150 plus GPS LOCATION OF SYSTH HORIZONTAL ACCURACY WILL THE SEWERAGE SY IF YES, ATTACH A PROFE DISTANCE OF PROPOSED	LAYER (cm): (m) 11 STEM BE LOCATED LI SSIONAL'S REPORT / SEWERAGE SYSTEM METHOD: THE PROPOSED SEWE DNFLICT WITH LEGA	OF THE SOIL ES) LATITUDE: 48.76855 ESS THAN 30m FROM A V AND SPECIFY THE INTEN TO THE CLOSEST SURF/ TYPE 1 ERAGE IS THIS FILIN FROM THE HE	IS ATTACK	HED YES	23.876330 DIFFEREN (n) UTYI SULT OF A	TTAL GPS m) PE 3
DRINKING WATER PROTECTION SYSTEM INFORMATION LEGAL OR REGULATORY CONSIDERATIONS	TABLE OR RESTRICTIVE 150 plus GPS LOCATION OF SYSTE HORIZONTAL ACCURACY WILL THE SEWERAGE SY IF YES, ATTACH A PROFE DISTANCE OF PROPOSED SEWERAGE TREATMENT I CONSTRUCTION OF T SYSTEM WILL NOT CO INSTRUMENTS REGIS PLOT PLAN (TO SCA THE PLANS AND SPI	LAYER (cm): M (DECIMAL DEGREI (m) 11 STEM BE LOCATED LI SSIONAL'S REPORT / SEWERAGE SYSTEM METHOD: THE PROPOSED SEWE DNFLICT WITH LEGA TERED ON THE PROP LE) AND SPECIFICAT ECIFICATIONS ARE C	OF THE SOIL ES) LATITUDE: 48.76855 ESS THAN 30m FROM A V AND SPECIFY THE INTEN TO THE CLOSEST SURFA TYPE 1 ERAGE L PERTY. IS THIS FILIN FROM THE HE PERTY. IONS ARE ATTACHED ONSISTENT WITH STAND	IS ATTACK	HED YES LONGITUDE: 12 AL GPS YES NO YES NO	23.876330 DIFFEREN (((m) (m) (TYI SULT OF A (R)	MTIAL GPS m) PE 3 NO ORDER NO
DRINKING WATER PROTECTION SYSTEM INFORMATION LEGAL OR REGULATORY CONSIDERATIONS PLOT PLAN AND SPECIFICATIONS	TABLE OR RESTRICTIVE 150 plus GPS LOCATION OF SYSTE HORIZONTAL ACCURACY WILL THE SEWERAGE SY: IF YES, ATTACH A PROFE DISTANCE OF PROPOSED SEWERAGE TREATMENT I CONSTRUCTION OF T SYSTEM WILL NOT CO INSTRUMENTS REGIS PLOT PLAN (TO SCA THE PLANS AND SPI SOURCE OF STANDARD P	LAYER (cm): M (DECIMAL DEGREI (m) 11 STEM BE LOCATED LI SSIONAL'S REPORT / SEWERAGE SYSTEM METHOD: THE PROPOSED SEWE DNFLICT WITH LEGA TERED ON THE PROP LE) AND SPECIFICAT ECIFICATIONS ARE C	OF THE SOIL ES) LATITUDE: 48.76855 ESS THAN 30m FROM A V AND SPECIFY THE INTEN TO THE CLOSEST SURFA TYPE 1 ERAGE L PERTY. TONS ARE ATTACHED	IS ATTACK	HED YES LONGITUDE: 12 AL GPS I YES NO NCE n/a 2 30 plus PE 2 TED AS THE RES HORITY? YOF THE ORDE	23.876330 DIFFEREN (((m) DI TYI SULT OF A R)	MTIAL GPS m) PE 3 NO ORDER NO
SYSTEM INFORMATION LEGAL OR REGULATORY CONSIDERATIONS	TABLE OR RESTRICTIVE 150 plus GPS LOCATION OF SYSTE HORIZONTAL ACCURACY WILL THE SEWERAGE SY IF YES, ATTACH A PROFE DISTANCE OF PROPOSED SEWERAGE TREATMENT I CONSTRUCTION OF T SYSTEM WILL NOT CO INSTRUMENTS REGIS PLOT PLAN (TO SCA THE PLANS AND SPI	LAYER (cm): M (DECIMAL DEGREI (m) STEM BE LOCATED LI SSIONAL'S REPORT / SEWERAGE SYSTEM METHOD: THE PROPOSED SEWE DNFLICT WITH LEGA TERED ON THE PROI DNFLICT WITH LEGA TERED ON THE PROI LE) AND SPECIFICAT ECIFICATIONS ARE C RACTICE: MI	OF THE SOIL ES) LATITUDE: 48.76855 ESS THAN 30m FROM A V AND SPECIFY THE INTEN TO THE CLOSEST SURFA TYPE 1 ERAGE L PERTY. IONS ARE ATTACHED ONSISTENT WITH STAND INISTRY OF HEALTH STAND	IS ATTACK	HED YES LONGITUDE: 12 AL GPS I YES NO NCE n/a 2 30 plus PE 2 TED AS THE RES HORITY? YOF THE ORDE TTICE ACCERCE/MANUAL PLUNG ACCEPTED MUSY U D ZU	23.876330 DIFFEREN (((m) () SULT OF A R)	MTIAL GPS m) PE 3 NO ORDER NO
DRINKING WATER PROTECTION SYSTEM INFORMATION LEGAL OR REGULATORY CONSIDERATIONS PLOT PLAN AND SPECIFICATIONS	TABLE OR RESTRICTIVE 150 plus GPS LOCATION OF SYSTE HORIZONTAL ACCURACY WILL THE SEWERAGE SY: IF YES, ATTACH A PROFE DISTANCE OF PROPOSED SEWERAGE TREATMENT I CONSTRUCTION OF T SYSTEM WILL NOT CO INSTRUMENTS REGIS PLOT PLAN (TO SCA THE PLANS AND SPI SOURCE OF STANDARD P	LAYER (cm): M (DECIMAL DEGREI (m) STEM BE LOCATED LI SSIONAL'S REPORT / SEWERAGE SYSTEM METHOD: THE PROPOSED SEWE DNFLICT WITH LEGA TERED ON THE PROI DNFLICT WITH LEGA TERED ON THE PROI LE) AND SPECIFICAT ECIFICATIONS ARE C RACTICE: MI	OF THE SOIL ES) LATITUDE: 48.76855 ESS THAN 30m FROM A V AND SPECIFY THE INTEN TO THE CLOSEST SURFA TYPE 1 TYPE 1 TYPE 1 TAGE L PERTY. IS THIS FILIN FROM THE HE PERTY. IS THE CLOSEST SURFA	IS ATTACK	HED YES	23.876330 DIFFEREN (((m)) DIFFEREN (m) (m) (m) (m) (m) (m) (m) (m) (m) (m)	MTIAL GPS m) PE 3 NO ORDER NO





Office: (250) 746-4277 Fax: (250) 746-4257

Email: skseptics@shaw.ca Web: www.skseptics.ca

5881 Howard Ave, Duncan B.C. V9L 3N7

Onsite Wastewater Site Assessment and Construction Specifications

May 6, 2024 Owners: Ina Cline Site: 5592 Riverbottom Road Phone: 250 710 5363 Legal: Description: Parcel D, Section 7, Range 1, Sahtlam Land District, Except Plan 13329 (DD 360651) and of Range 2 Folio # 03503.180 PID: 000 - 006 - 076 GPS location: Latitude - 48.779765 Longitude - 123.791713

System Summary

3 Bedroom House (Residential only) Total Living Area allowed: 280m² (3014 ft²) Daily Design Flow rate (DDF): 1300 LPD (286 GPD) Expected Average Daily flows: 650 LPD (143 GPD) System: Type 1 Pressure distribution to a seepage bed Hydraulic Loading Rate chosen: 32 Area of infiltrative surface (AIS) = DDF/HLR = 41 LLR 170 1300 LPD/170 LLR = 7.65m in length, (25 feet) Min. discharge area length Rock bed area is 3m wide X 13.5m in length

Site Evaluation

Owner wants to have a new sewerage system designed for a 3 bedroom house. After looking at test pits results I found there is enough soil for a pressure distribution to seepage bed system.

Some C 33 sand to be placed on AIS bed area.



Specifications for proposed Sewerage system at 5592 West Riverbottom Road

Page 1 of 4

MAY 0 6 2024

Test Pit Soil Evaluation

Test Pit 1

- 0 10cm: Lawn, Brown, Loose, Many roots
- 10-57cm: Very fine sandy loam, small 1-3cm
- peds, common roots, 4% rocks and coarse fraction, Very dark
- 57 150cm Very gravely. Course sand and bigger rocks


Constraints and design rationale

Constraints	Mitigating Strategies
Sewer line from house to deep for a gravity system. Discharge area will be raised to keep surface water away. Some loam will need to be removed and later used for cover on top of discharge area	Presure distribution to a seepage bed discharge system Discharge area will be raised to keep surface water away. Will also dig out the Joamy soil and replace with 18" of C 33 Sand to give some treament before draining into the course gravel horizen and selected 32 HLR do to this.

Tanks

New 1000 Gallon two compartment septic tank with an effluent filter

New 600 Gallon one compartment pump tank



Specifications for proposed Sewerage system at 5592 West Riverbottom Road

Page 2 of 4

Installer must:

- Inspect tank prior to installation to ensure tank is not damaged;
- Perform a water tightness test as described in SPM
- Backfill the tank evenly on all four sides in 30 cm (12") lifts with compaction to final grade (or use suitable clean rock)
- >

Pump Settings

Rhombus Indoor outdoor alarm will be set on demand dose to pump approximately 27 Gallons per pump cycle. The audible and visual alarm is part of the panel.

Discharge area

All work to follow the Standard Practice Manual. All Pipe to be CSA approved Type 1 Pressurized to Seepage bed

Excavation for receiving area, mound sand and pea-gravel bed

Installer is to excavate into approximately 55cm of native soil, then place 45cm of C- 33 Sand.

Then Place 9" of clean drain rock, Then install 4 - 11/4" PVC lines, Orifice shields will cover 11/64

orifice, then rock will cover all PVC pipe, Filter cloth and then 7" of soil.

Rock Bed Size and Piping information

- 4 Laterals that are end fed run the length of rock bed
- Lateral spacing is 45cm from the outside edge
 - 60cm between laterals
- Orifice spacing is 76cm (30 inches) on the pipe
 - o 11/64 orifice size
 - o Orifice shields will cover the drilled holes
 - o Lateral length is 13.5.m (45 feet)
- The manifold is 2 inch CSA PVC
- Flush-outs are installed at the end of each line with 2 45degree fittings

Specifications for proposed Sewerage system at 5592 West Riverbottom Road

RECEIVED MAY 0 6 2024

Page 3 of 4

- Ball valves to control each lateral at the start of each line
- All flush-outs and valves for the discharge area have proper valve-boxes to cover them in order to provide protection and later access

Qualified Installer:

- If qualified installer is other than Stewart Krumm site inspection fees will apply
- Must contact Stewart Krumm at least 2 weeks prior to installation for <u>a required</u> site meeting
- All work to follow the Standard Practice Manual.
- All PVC pipe must be CSA approved
- Insure that all components, lids, sidewalks, driveways, street etc. are left as clean as For answers to any questions of concerns please contact:

Stewart Krumm


(250) 709-4497

skseptics@shaw.ca

RE	CE	1	/EL	5
M/	Y O	6 2	024	

Specifications for proposed Sewerage system at 5592 West Riverbottom Road

Page 4 of 4



nput Parameters	Dec	<u>e</u> (line Riverb	otte	2m		
	11/04		Calculation	_	2000021A	Size Pump For	
Orifice Size Residual Head at Last Orifice	·	inches	Minimum Flow Rate per Orifice	0.73		Design Flow Rate	56.4 gpm
Orifice Spacing		feet	Number of Onifices per Zone	76		Total Dynamic Head	23.3 feet
Number of Laterals per Cel		loof.	Total Flow Rate per Zone	56.4			
Lateral Length	1	feet	Number of Laterals per Zon∈ % Flow Differential 1st and Last Orifice	4	%	Pressure head desired	at most distant
Lateral Pipe Class/Schedule		leet	% Flow Diverential 1st and Last Onnice	5.1	70	orifice in distribution late values range from 1 foo	t to 5 feet
Lateral Line Size		inches	Static Heads			depending upon orifice	size.
Distributing Valve Model		in the fight	Lift to Manifold	11.0	feet		
Manifold Length	ليت ا	feet	Residual Head at Last Orifice	4.0	1000	1	
Manifold Pipe Class/Schedule				1.5	NOC1		
Manifold Line Size	·	inches	Frictional Head Losses				
Lift to Manifold	·	feet	Head Loss in Laterals	0.5	feet		
Transport Length		feet	Head Loss through Distributing Valve	0.0		Calculate	
ransport Pipe Class/Schedule		1935) D	Head Loss in Manifold	0.7	feet		
Transport Line Size		inches	Head Loss in Transport Pipe	0.8	feet	Generale Ch	neut
Discharge Assembly Size	2.00 -	inches	Head Loss through Discharge	6.4	feet		
Flow Meter	None 🔻	inches	Head Loss through Flow Meter	0.0	feet		
'Add-on' Friction Losses	0.0	feet	'Add-on' Friction Losses	0.0	feet		
				1	EWA	STEWAY	
				014	NA TEWART PL OWO	RECEIVI MAY 0 6 20	24

